

- Site Report -

Date: September 26, 2012

IRD Sales Order: To: Cindy Mantie From: Bryan Knight

Project Name/Location: LTPP Deming, NM

Service Date(s): March 10 2010

Job Description: Communication Lost with Site

Work Completed:

• Arrived onsite and found no power at cabinet.

• Troubleshooting led to a blown 10A isolation fuse. Replaced fuse and power restored.

• ISINC powered up normally. Logged onto site and verified sensor operation OK.

• Verified Solar Battery Charger operating normally: Battery 14.4V, Solar Output 3A, Load .3A.

6/19/96 IRD FORM No.: 1304A





Work Remaining:

Parts Used: 1x 10A Fuse

Pre-mature Equipment Failure:

Mileage / Travel Time: Total Travel: 6hrs Total Onsite: 1hr

Safety Concerns:

Issues Related to Sub-Contractors:

Other Notes:

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		